RICHY FIVE DEPARTURE

SL-5416 (FAA)



DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RUNWAY 36: Turn left heading 330°. Intercept SWR R-117 at or above 8300', continue climb northwest bound on SWR R-117 to SWR VOR/DME. Cross SWR VOR/DME at or above 11,000'. Aircraft cleared via a transition, reverse course to the left after crossing the SWR VOR/DME, and proceed to RICHY INT via SWR R-117. Cross RICHY INT at 12,000'. Southeast and Southwest bound, thence (via transition).

GENNE TRANSITION (RICHY5.GENNE): From over RICHY INT via SWR R-117 to GENNE INT. Cross MARRI INT at 13,000'. Expect further clearance to filed altitude after MARRI INT.

MARRI TRANSITION (RICHY5.MARRI): From over RICHY INT via SWR R-117 to MARRI INT Cross MARRI INT at 13,000'. Expect further clearance to filed altitude after MARRI INT.

SPOOK TRANSITION (RICHY5.SPOOK): From over RICHY INT via FMG R-192 to SPOOK INT. Expect further clearance to filed altitude after SPOOK INT.

TILTS TRANSITION (RICHY5.TILTS): From over RICHY INT via SWR R-117 to TILTS INT. Cross MARRI INT at 13,000'. Expect further clearance to filed altitude after MARRI INT.